

1. Introduction




Welcome to choose this product!

This is a kind of 3 1/2 bit portable digital Clamp-Shape meter, which may measure AC current and AC & DC voltage, resistance, test for connection and disconnection, positive voltage on diode, etc... The meter is the ideal tool of the industries of electricity, electronics and refrigeration due to wonderful structure, easily operated, more portable.

2. Safety

The meter is designed in accordance with the safety requirements of the standard IEC1010-1. Please Carefully read this manual before operate it.

2.1 Note for safety symbols:

-  Warning hint, Caution!
-  Danger by high-voltage shock!
-  Double insulation protection

2.2 During measuring, any range may not exceed its input value in Max

2.3 At resistance range, not allowed to impose voltage on input

2.4 During measuring, to prevent the meter from damage, do not turn its round switch to change its range.

2.5 Over DC60V or AC30V may be shock danger, carefully operating during measuring.

2.6 During clamping non-insulation wire, must specially be careful to avoid

2.7 During measuring current, fingers must be placed on the back of the armguard of the meter.

2.8 The meter shall avoid straight sunlight, high temperature and humidity.

2.9 After measuring end, the turning switch shall be at OFF.

2.10 Idling for long term, its batteries shall be taken out to prevent the batteries from leaking liquid to damage parts.


3. Features

3.1 Displaying mode: LCD displayer

3.2 Maximum display: 1999

3.3 Maximum open: 30mm

3.4 Automatic negative indication: Displaying “-“

3.5 Low battery indication: Displaying “”

3.6 Auto power off

3.7 Operating environment: 0°C~40°C, 70%RH(Max.)

3.8 Storage environment: -20°C~60°C, 85%RH(Max.)

3.9 Power supply: 9V battery (IEC6F22, NEDA1604, JIS006P or equivalent types).

3.10 Size 221 (Length) × 75 (Width) × 31 (Height) mm

3.11 Weight: about 240gram (with batteries)


4. Usage of Clamp Meter

4.1 Instruction on operating panel (see figure)

- (1) Clamp mouth
- (2) Trigger
- (3) Range switch: choosing current, voltage, resistance, forward voltage on diode, test for connection and

disconnection and range.

- (4) DH reading holding button: pressing the button may lock the current reading, and displaying “DH” symbol, repressing the button to cancel the holding function, “DH” symbol disappears.
- (5) LCD
- (6) ”COM” for common input (input ground)
- (7) “V/Ω”voltage-resistance input jack
- (8) Armguard



4.2 Measurement of AC voltage


Turn the range switch into the range “A600V”, Plug the black pen into the jack“COM”, the red pen into the jack“V/Ω”, in parallel connect the pens with the measured circuit, read the displaying number.

4.3 Measurement of DC voltage

Turn the range switch into the range “D600V”, Plug the black pen into the jack“COM”, the red pen into the jack“V/Ω”, in parallel connect the pens with the measured circuit, read the displaying number. When the reading is less than 20V, turn the range switch at range ”DC20V” to measure again.

4.4 Measurement of AC current


Turn the range switch into the range “AC600A”, clamp the wire of the measured current, shall put the wire into the center of the completely closing clamp mouth as soon as possible, directly get the reading. When the reading is less, turn the range switch at lower range to measure again.

 **Cautions:** If two or more than two different wires are clamped, the measuring can't be done.


4.5 Measurement of resistor

- (1) Turn the range switch into the range 2kΩ
- (2) plug the black pen into the jack“COM”, the red pen into the jack“V/Ω”
- (3) In parallel connect the pens into the two terminators of the measured circuit or component, get the reading.
- (4) when the two pens open or input overload, the displayer shows “1”

4.6 Measurement of forward voltage of diode

- (1) Turn the range switch into the range , when the input opens, the meter shows over range (show“1”).
- (2) Plug the black pen into the jack“COM”, the red pen into the jack“V/Ω”, (the red pen's polarity is“+”)
- (3) In parallel connect the pens into the two terminators of the measured diode, get the reading for approximation of the forward voltage.
- (4) when the diode is connected in reverse or the input open, the displayer shall show “1”.


4.7 Test of connection and disconnection

- (1) Turn the range switch into the range , when the input



opens, the meter shall show over range (show “1”).

(2) Plug the black pen into the jack“COM”, the red into the jack“V/Ω”。

(3) In parallel connect the two pens into the two terminators of the measured circuit, if the resistance between the tested two points is less than approximate 50Ω, the buzzer shall make a sound.

 Cautions: resistor, diode and connection and disconnection sharing the same range, when measuring, the measured component or circuit cannot be electrified, otherwise, shall misjudge.

5. Technological Indices


Function	Range	Resolution	Accuracy
ACA	2A	1mA	±1.9%±5
	20A	10mA	
	200A	100mA	
	600A	1A	
ACV	600V	1V	±1.2%±5d
DCV	20V	0.01V	±0.8%±2d
	600V	1V	
Resistor	2kΩ	1Ω	±1.0%±2d
Diode 	Show the value of the forward voltage. Test conditions: forward DC current is about 1mA, backward DC voltage is about 2.8V。		
Connection & disconnection 	When Conductive resistance is less than about 50Ω, the buzzer in the meter sounds, test conditions: open voltage is about 2.8V。		


OHM/Diode/Connection Overload protection:250V

Accuracy guarantee: 1 year , Temperature of keeping accuracy:23℃±5℃

Relative humidity:<75 %。

6. Maintenance of the Meter

 Cautions! Before open the covers of the meter, or the batteries, shall switch off power and disconnect the pens and any input signal to prevent danger of shock.

6.1 when the meter shows symbol“”, shall change battery. Open the battery cover, change a fresh battery with 9V , to make sure the meter normal work.

6.2 Keep the meter and the pens clean, dry and non-damage, may clean the meter surface with clean clothes or eradicator, abrasive or organic solvent is banned.

6.3 Avoid mechanical damage, shake, impact, keep the meter away from high temperature and strong magnet field.

6.4 The meter shall be calibrated once a year.

7. Accessories

7.1 A pair of pen

7.2 A manual